

00684.003266.



*Co/C*  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Takeshi Yasumoto, et al.

Appln. No.: 09/978,213

Filed: October 17, 2001

For: DRIVING FORCE TRANSMISSION  
MECHANISM, IMAGE FORMING  
APPARATUS EQUIPPED WITH SUCH A  
MECHANISM, AND PROCESS UNIT OF  
SUCH AN APPARATUS

: Examiner: Sandra Brase

: Group Art Unit: 2852

: Patent No.: US 6,829,455

: Issued: December 7, 2004

: March 9, 2005

*Certificate*

*MAR 15 2005*

*of Correction*

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Attention: CERTIFICATE OF CORRECTION BRANCH**

**REQUEST FOR CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such

Certificate of Correction.

03/10/2005 LWONDIM2 00000041 6829455


01 FC:1811

100.00 OP

*MAR 16 2005*

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,



Gary M. Jacobs  
Attorney for Patentees  
Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2200

GMJ/lwise 192470

DC\_MAIN 192470v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,829,455 B1

DATED : December 7, 2004

INVENTOR(S) : YASUMOTO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 3, "photosensitive" should read --photosensitive member--.

COLUMN 5:

Line 43, "comprises" should read --comprise--.

COLUMN 9:

Line 57, "holes the" should read --the holes--.

COLUMN 12:

Line 18, "ments" should read --ment--.

COLUMN 19:

Line 18, "potion 10" should read --portion 10--.

Line 33, "driving system" should read --driven system--.

Line 47, "this" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,829,455 B1

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,829,455 B1

DATED : December 7, 2004

INVENTOR(S) : YASUMOTO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4:

Line 3, "photosensitive" should read --photosensitive member--.

COLUMN 5:

Line 43, "comprises" should read --comprise--.

COLUMN 9:

Line 57, "holes the" should read --the holes--.

COLUMN 12:

Line 18, "ments" should read --ment--.

COLUMN 19:

Line 18, "potion 10" should read --portion 10--.

Line 33, "driving system" should read --driven system--.

Line 47, "this" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,829,455 B1

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

00684.003266.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Takeshi Yasumoto, et al.

Appn. No.: 09/978,213

Filed: October 17, 2001

For: DRIVING FORCE TRANSMISSION  
MECHANISM, IMAGE FORMING  
APPARATUS EQUIPPED WITH SUCH A  
MECHANISM, AND PROCESS UNIT OF  
SUCH AN APPARATUS

: Examiner: Sandra Brase  
):  
: Group Art Unit: 2852  
):  
: Patent No.: US 6,829,455  
):  
: Issued: December 7, 2004  
):  
: March 9, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Attention: CERTIFICATE OF CORRECTION BRANCH**

**REQUEST FOR CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323**

Sir:


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

MAR 16 2005

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,



Gary M. Jacobs  
Attorney for Patentees  
Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2200

GMJ/lwise 192470

DC\_MAIN 192470v1

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,829,455 B1

DATED : December 7, 2004

INVENTOR(S) : YASUMOTO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 4:**

Line 3, "photosensitive" should read --photosensitive member--.

**COLUMN 5:**

Line 43, "comprises" should read --comprise--.

**COLUMN 9:**

Line 57, "holes the" should read --the holes--.

**COLUMN 12:**

Line 18, "ments" should read --ment--.

**COLUMN 19:**

Line 18, "portion 10" should read --portion 10--.

Line 33, "driving system" should read --driven system--.

Line 47, "this" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,829,455 B1

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,829,455 B1

DATED : December 7, 2004

INVENTOR(S) : YASUMOTO, ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 4:**

Line 3, "photosensitive" should read --photosensitive member--.

**COLUMN 5:**

Line 43, "comprises" should read --comprise--.

**COLUMN 9:**

Line 57, "holes the" should read --the holes--.

**COLUMN 12:**

Line 18, "ments" should read --ment--.

**COLUMN 19:**

Line 18, "potion 10" should read --portion 10--.

Line 33, "driving system" should read --driven system--.

Line 47, "this" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,829,455 B1

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

MAR 16 2005